

Important – Always read and follow the care instructions and any warnings provided by the carpet manufacturer. Carpets made with natural fibers and/or certain dyes may require special treatment. If in doubt, contact the manufacturer for advice prior to cleaning.

- Saturate spot with lemon juice, using a spray bottle, and allow to remain for 5 minutes.
- Blot up as much of the liquid as possible with a white paper towel or terry cloth.
- Apply Crystal Spotter® to the affected area. Use a blotting motion to work the Crystal Spotter® into the affected area. If spot is coming up, continue applying Crystal Spotter® and blotting with a white paper towel or terry cloth until spot is removed.
- Spray lightly with Crystal Spotter®. Do not blot at this time. Apply a pad of paper towels and weight (such as a brick) and allow to dry.
- If there is still some stain on the carpet and blotting is not removing it, moisten the tufts in the stained area with 3% hydrogen peroxide. Let stand for one hour. Blot and repeat until carpet is stain free. Ambient light will cause hydrogen peroxide to change into water, so rinsing is not necessary. Apply paper towels with weight and allow to dry.
- Apply Crystal Spotter® and agitate/pile lift with Carpet Roamer® Spotting Tool.

Visit www.whittakersystem.com to learn more about carpet maintenance using Crystal Dry® products.